VEOLIA
WATER

April 5, 2009

Marcia St. Martin
Director N.O. S&WB
S&WB of New Orleans
625 St. Joseph Street
New Orleans, LA 70130

Re: Quarterly Report – Fluid Bed Incineration Operation and Maintenance

Dear Ms. St. Martin:

The enclosed report satisfies all conditions set forth in the Fluid Bed Incinerator's Operations and Maintenance Plan. Additionally, the report is accordance with 40 CFR Part 60, Subpart A&O; 40 CFR Part 60, Subpart A, δ60.7 and 40 CFR Part 503; 40 CFR Part 61, Subpart C and E.

Please note that the Fluid Bed Incinerator was returned to service on August 8, 2008, well ahead of the established December 15, 2008 deadline. The Fluid Bed Incinerator was severely damaged by the winds and tidal surge associated with **Hurricane Katrina**. The catastrophic damage required 5.5 million dollars in repairs to return the unit to pre-Katrina conditions. An initial start up period of 180 days is allowed under our existing air permit #2140-00089-02 general condition VIII and IX.

A successful Emission Compliance Test (FBI stack test) was completed on January 27, 2009 satisfying all conditions of the Louisiana Department of Environmental Quality's air permit #2140-00089-02. The test was conducted using EPA methods 1-5, 6C, 7E, 10, 25A & 29.

If any questions arise during the review of this report, please do hesitate to contact me at 504-277-5400.

Sincerely,

K. Servat

Kevin Servat
Project Manager
Veolia Water, New Orleans

Veolia Water North America Operating Services, LLC
6501 Florida Avenue, New Orleans, LA 70117
Tel: 504.277.5400 • Cell: 504.628.2628
www.veoliawaterna.com