## **Two-Week Look-Ahead Schedule**

**Contractor: BLD Services LLC** 

Project Name and Number: #30229, Carrollton Basin No. 1

**Submitted By: Nicholas Dupaquier** 

Submission Date: 4/25/25

Time Period Covered: 4/25/25-5/9/25

--

## **Planned Work Activities**

Date	Block Number and	Work to be Performed	Notes
	Street Name		
4/25/25-	2500 S Carrollton	Coordinating other repair options to avoid	TBD <b>– BLD</b>
5/9/25		pipe bursting in this area	
4/25/25-	8500 S Claiborne	CCTV	TBD – <b>BLD</b>
5/9/25	Ave		
4/25/25-	8200 Stroelitz	CIPP	TBD - <b>BLD</b>
5/9/25			
4/25/25-	9400 Oleander St	Active water leak preventing CIPP work	TBD - <b>BLD</b>
5/9/25			
4/25/25-	2700 Cherry	CCTV	TBD - <b>BLD</b>
5/9/25			
4/25/25-	8200 Palmetto	Restoration	TBD <b>– C&amp;M</b>
5/9/25			
4/25/25-	5000 Academy	CIPP	TBD - <b>BLD</b>
5/9/25			
4/25/25-	8300 S Claiborne	CIPP	TBD - <b>BLD</b>
5/9/25			
4/25/25-	3200 Dublin	CIPP	TBD - <b>BLD</b>
5/9/25			
4/25/25-	9500 Palmetto	Restoration	Pouring concrete, sidewalks and driveways, site
5/9/25			cleanup – C&M
4/25/25-	3500 Leonidas	Restoration	Pouring concrete, sidewalks and driveways, site
5/9/25			cleanup – C&M
4/25/25-	3400 Eagle, 8800	Restoration	Pouring concrete, sidewalks and driveways, site
5/9/25	Colapissa, 8300		cleanup – C&M
	Colapissa, 9100		
	Apricot, 2600 Cherry		

4/25/25-	9100 Apricot	Restoration	Grading, Forming, Pouring – <b>C&amp;M</b>
5/9/25			

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

Restoration Work on-going across the basin.

**BLD TRACKING: 88% COMPLETE** 

With the river reaching above 11', we are required to stop any new excavation. This includes repairs and restoration efforts within 1500' of the levee. Any on-going work that has already been excavated can continue as normal.