## **Two-Week Look-Ahead Schedule**

**Contractor: BLD Services LLC** 

Project Name and Number: #30230, Carrollton Basin No. 2

**Submitted By: Nicholas Dupaquier** 

**Submission Date: 3/10/25** 

Time Period Covered: 3/10/25-3/21/25

--

## **Planned Work Activities**

| Date     | Block Number and<br>Street Name | Work to be Performed                                 | Notes  |
|----------|---------------------------------|--|--|
| 3/10/25- | 7700 Claiborne                  | CIPP   | No impacts to traffic – BLD                                  |
| 3/10/25- | 7700 Ctalborne                  | GIFF   | No impacts to traine – BLD                                   |
| 3/21/25  | 600 Pine                        | LAT CIPP   | No impacts to traffic, schedule TBD – BLD                    |
| 3/21/25  | 0001 iiie                       | LAI OII I  | No impacts to traine, schedule 100 - 010                     |
| 3/10/25- | 7200 Green                      | LAT CIPP   | No impacts to traffic, schedule TBD – <b>BLD</b>             |
| 3/21/25  | 7200 010011                     | Dit on t   | No impuets to traine, seriodate 155 525                      |
| 3/10/25- | 7200 Birch                      | LAT CIPP   | No impacts to traffic, schedule TBD - <b>BLD</b>             |
| 3/21/25  | 7200 8.11011                    | 2 3 1  | The impacts to trains, constant 125 225                      |
| 3/10/25- | 7100 Green                      | Restoration  | Pouring, site cleanup – <b>C&amp;M</b>                       |
| 3/21/25  |                                 |  | 3,   |
| 3/10/25- | 2300 Pine                       | Restoration  | Removal, Grading, Forming, Pouring – <b>C&amp;M</b>          |
| 3/21/25  |                                 |  |  |
| 3/10/25- | 2100 Pine                       | Restoration  | Removal, Grading, Forming, Pouring – <b>C&amp;M</b>          |
| 3/21/25  |                                 |  |  |
| 3/10/25- | 2000 Pine                       | Restoration  | Grading, Forming, Pouring – C&M                              |
| 3/21/25  |                                 |  |  |
| 3/10/25- | 1900 Pine                       | Restoration (waterline conflict issue resolved       | Grading, Forming, Pouring – <b>C&amp;M</b>                   |
| 3/21/25  |                                 | proceeding with restoration)                         |  |
| 3/10/25- | 1800 Pine                       | Restoration – ON HOLD PENDING LEAD WATER             | TBD – <b>C&amp;M</b>   |
| 3/21/25  |                                 | SERVICE LINE EFFORT                                  |  |
| 3/10/25- | 1700 Pine                       | Restoration  | Grading, Forming, Pouring – <b>C&amp;M</b>                   |
| 3/21/25  |                                 |  |  |
| 3/10/25- | 1000 Pine St                    | PR 320-DSMH  | On Hold due to valve box conflict (20" WL) –ON HOLD          |
| 3/21/25  |                                 |  | DUE TO 20" WATER MAIN LEAK IN AREA                           |
| 3/10/25- | 7200 Spruce St                  | PR 0-12, PR 194-206 (on hold due to tree permitting, | Work will be ~1 day for each repair location. The road       |
| 3/21/25  |                                 | required for air spading                             | will be open at the close of each day. – Cooper Construction |

TREE IMPACT ON 7200 SPRUCE – REROUTE LATERAL AROUND TREE CONFLICT (NO IMPACT TO TREE, BUT WE WILL NEED ARBORIST ASSISTANCE AND PERMITTING FROM PARKS AND PARKWAYS)

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

MH rehab on-going

**BLD TRACKING: 88% COMPLETE**