Contractor: BLD Services LLC

Project Name and Number: #30229, Carrollton Basin No. 1

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25- 1/31/25	9000 Nelson	PR USMH, PR DSMH	1/23/25 – Cooper Construction
1/17/25- 1/31/25	3000 Monroe	ML CIPP	No impacts to traffic, schedule TBD – BLD
1/17/25- 1/31/25	9400 Oleander St	Active water leak preventing CIPP work	TBD - BLD
1/17/25- 1/31/25	3600 Dante St	Active water leak preventing CIPP work	TBD - BLD
1/17/25- 1/31/25	3800/3900 Cambronne	ML Repairs, MH Vertical Adjustment	Tentatively scheduled for 1/22/25 - BLD
1/17/25- 1/31/25	8200 Claiborne	ML Repairs	Tentatively scheduled for 1/20/25 - BLD
1/17/25- 1/31/25	2800 Monticello	Restoration	Site cleanup – C&M
1/17/25- 1/31/25	9400 Oleander	Restoration	Site cleanup – C&M
1/17/25- 1/31/25	3700 Livingston	Restoration	Site cleanup – C&M
1/17/25- 1/31/25	8300 Colapissa	Restoration	Site cleanup – C&M

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

Restoration Work on-going across the basin.

BLD TRACKING: 79% COMPLETE

Contractor: BLD Services LLC

Project Name and Number: #30230, Carrollton Basin No. 2

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25-	700 Audubon	CIPP	No impacts to traffic – BLD
1/31/25			
1/17/25-	7200 Green	LAT CIPP	No impacts to traffic, schedule TBD – BLD
1/31/25			
1/17/25-	7200 Birch	LAT CIPP	No impacts to traffic, schedule TBD - BLD
1/31/25			
1/17/25-	7100 Green	Restoration	Pouring, site cleanup – C&M
1/31/25			
1/17/25-	2300 Pine	Restoration	Pouring, site cleanup – C&M
1/31/25			
1/17/25-	2000 Pine	Restoration	Pouring, site cleanup – C&M
1/31/25			
1/17/25-	1700 Pine	Restoration	Pouring, site cleanup – C&M
1/31/25			
1/17/25-	1000 Pine St	PR 320-DSMH	On Hold due to valve box conflict (20" WL) –
1/31/25			SWBNO/Stantec/BLD discussing options
1/17/25-	7200 Spruce St	PR 0-12, PR 194-206 (on hold due to tree	Work will be ~1 day for each repair location. The road will be
1/31/25		permitting, required for air spading	open at the close of each day Cooper Construction

TREE IMPACT ON 7200 SPRUCE – REROUTE LATERAL AROUND TREE CONFLICT (NO IMPACT TO TREE, BUT WE WILL NEED ARBORIST ASSISTANCE AND PERMITTING FROM PARKS AND PARKWAYS)

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

MH rehab on-going

BLD TRACKING: 78% COMPLETE

Contractor: BLD Services LLC

Project Name and Number: #30232, Carrollton Basin No. 3

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25-	400 Walnut	CIPP (pending post CCTV)	~4-6hrs., minimal impacts to traffic - BLD
1/31/25			
1/17/25-	400 Broadway	LAT CIPP	~4-6hrs., minimal impacts to traffic – BLD
1/31/25			
1/17/25-	300 Broadway	LAT CIPP	~4-6hrs., minimal impacts to traffic – BLD
1/31/25			
1/17/25-	300 Pine	LAT CIPP	~4-6hrs., minimal impacts to traffic – BLD
1/31/25			
1/17/25-	7100 Pitt	Restoration (mill and overlay scheduled	Wearing, site cleanup – C&M
1/31/25		1/20)	
1/17/25-	100, 200,300 Walnut / 7000 Constance / 200 Audubon	Restoration (mill and overlay scheduled 1/6)	Milling/Overlay – C&M
1/31/25	Constance / 200 Audubon		
1/17/25-	7300 Garfield	Restoration (mill and overlay scheduled	Pouring, site cleanup – C&M
1/31/25		1/20)	
1/17/25-	400 Walnut	Restoration (mill and overlay scheduled	Pouring, site cleanup – C&M
1/31/25		1/20)	
1/17/25-	500 Walnut	Restoration (mill and overlay scheduled	Pouring, site cleanup – C&M
1/31/25		1/20)	
1/17/25-	7000 Benajmin	Restoration (mill and overlay scheduled for	Pouring, site cleanup – C&M
1/31/25		1/20)	
1/17/25-	500-300 Broadway	Restoration (Excavate 1/17, mill and overlay	1st Half Excavation, Grading, Forming – C&M
1/31/25		2/10)	
1/17/25-	400 Broadway	Restoration (Sawcut completed, Excavate	Excavation – C&M
1/31/25		1/17, mill and overlay 2/10)	

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each work day; repairs are scheduled to take ~1day each.

MH rehab on-going

BLD TRACKING: 88% COMPLETE

Contractor: BLD Services LLC

Project Name and Number: #30235, Carrollton Basin No. 5

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25-	7400 Freret	ML CIPP	~4-6 hrs., minimal impact to traffic - BLD
1/31/25			
1/17/25-	8900 Birch	ML CIPP – Work delayed due to obstruction	~4-6 hrs., minimal impact to traffic – BLD
1/31/25		surcharging area (removed)	
1/17/25-	1400 Monticello	ML CIPP – Work delayed due to obstruction	~4-6 hrs., minimal impact to traffic – BLD
1/31/25		surcharging area (removed)	
1/17/25-	Monticello Segment	ML CIPP – Work delayed due to obstruction	~4-6 hrs., minimal impact to traffic – BLD
1/31/25	(5-20B)	surcharging area (removed)	
1/17/25-	7600 Willow	Repairs to follow 7500 Willow – PR 175-187,	1 day anticipated per repair, minimal traffic impact
1/31/25		PR 205-217, SR 124	(roads will be accessible each day post repair) - BLD
1/17/25-	1500 Leonidas	Restoration	Forming 1 st half, 1 st half pour, begin 2 nd half excavation
1/31/25			– C&M
1/17/25-	8700 Willow	Restoration	Excavation, forming, pouring – C&M
1/31/25			
1/17/25-	7800 Willow	Restoration	Excavation, Forming, pouring – C&M
1/31/25			

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each workday; repairs are scheduled to take ~1day each.

MH rehab on-going

BLD TRACKING: 61% COMPLETE

> Water leaks on Leonidas and Willow resolved by BLD/Cooper Construction last week

Contractor: BLD Services LLC

Project Name and Number: #30251, Carrollton Basin No. 10

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and	Work to be Performed	Notes
	Street Name		
1/17/25-	Erato St	30"+ CCTV Effort – First attempt unsuccessful	Weather pending (scheduled 1/23/25) – Night work –
1/31/25		due to amount of water flow in the pipe. The	BLD
		CCTV crew will retry with a bigger flow through	
		plug	

MH rehab on-going

No tree impacts anticipated in the next 2 weeks

BLD TRACKING: 98% COMPLETE

REMAINING WORK

- > CCTV 30"+ Segment on Erato Scheduled 1/13/25 (weather pending)
- > 2 short CIPP segments on Broad/Euphrosine (30' total) still has water coming into pipes, BLD will attempt to light cure these segments and CIPP them in coming week(s)

Contractor: BLD Services LLC

Project Name and Number: #30252, Carrollton Basin No. 11

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

--

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25- 1/31/25	4500 Euphrosine	USMH MH segment is lower than the DSMH segment which is causing drainage issues (no flow in pipe) – BLD will proceed with spring/obstruction removal and PR – CIPP installation may have complications with the slope of the pipe (CCTV crew believes at one point the DSMH was the USMH)	CCTV Segment week of 1/13/25 - BLD
1/17/25-	Jeanette St (ADDED	PR + CIPP	Tentatively scheduled to complete final PR 1/23/25 -
1/31/25	WORK)		Cooper Construction

MH rehab on-going

No tree impacts anticipated in the next 2 weeks

BLD TRACKING: 98% COMPLETE

REMAINING WORK

- > 4500 Euphrosine holding water due to segment having negative slope toward USMH Issued for PR/obstruction removal
- > 1 Repair remaining on added work Jeanette St (+CIPP, Restoration)

Contractor: BLD Services LLC

Project Name and Number: #30253, Carrollton Basin No. 12

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

__

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25 1/31/25		PR, CIPP, Fix Water Leak	Minimal traffic impacts – BLD

MH rehab on-going – Finish MH lining work in next 2 weeks (1/17/25-1/31/25)

No tree impacts anticipated in the next 2 weeks

BLD TRACKING: 98% COMPLETE

All original contract sewer work has been completed

REMAINING WORK (ADDED TO CONTRACT):

> 2500 Hamilton (RR Added Work) – Issued to construction crew to complete repairs

Contractor: BLD Services LLC

Project Name and Number: #30254, Carrollton Basin No. 13

Submitted By: Korey Clement Submission Date: 1/17/25

Time Period Covered: 1/17/25-1/31/25

__

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
1/17/25-	3800 Vincennes	Restoration	Sidewalks, Driveways– C&M
1/31/25			
1/17/25-	6200 Rocheblave	Restoration	Pouring – C&M
1/31/25			
1/17/25-	3500 Calhoun	Restoration	2 nd Half Concrete base, forming, pouring 1 st half – C&M
1/31/25			
1/17/25-	3400 Calhoun	Restoration	2 nd Half Concrete base, forming, pouring 1 st half – C&M
1/31/25			
1/17/25-	3300 Calhoun	Restoration	1 st half concrete base, forming, pouring – C&M
1/31/25			
1/17/25-	3600 Vincennes	Restoration	Sidewalks, Driveways – C&M
1/31/25			
1/17/25-	3500 Vincennes	Restoration	Sidewalks, Driveways – C&M
1/31/25			

No tree impacts anticipated in the next 2 weeks

BLD TRACKING: 98% COMPLETE

REMAINING WORK:

- > Restoration
 - O Note: Currently working in half sections
- > MH Rehab After Restoration (MH Adjustment(s), Replace Frame and Cover)