Two-Week Look-Ahead Schedule

Contractor: BLD Services LLC

Project Name and Number: #30232, Carrollton Basin No. 3 Submitted By: Nicholas Dupaquier Submission Date: 3/14/25 Time Period Covered: 3/14/25-3/28/25

Planned Work Activities

Date	Block Number and Street Name	Work to be Performed	Notes
3/14/25-	200 Walnut	SR 69/71, SR 98, SR 192, SR 218, SR 249, SR	Work resumed, scheduled to re-mobilize 3/17–
3/28/25		279, SR 313	BLD
3/14/25-	7300 Hurst	SR 76/79, PR 162-174, SR 194, SR 219	Work resumed, scheduled to re-mobilize 3/17–
3/28/25			BLD
3/14/25-	400 Broadway	LAT CIPP (unable to complete due to	~4-6hrs., minimal impacts to traffic – BLD
3/28/25		surcharge)	
3/14/25-	300 Broadway	LAT CIPP (unable to complete due to	~4-6hrs., minimal impacts to traffic – BLD
3/28/25		surcharge)	
3/14/25-	7100 Pitt	Restoration	Wearing, site cleanup – C&M
3/28/25			
3/14/25-	7300 Garfield	Restoration	Pouring, site cleanup – C&M
3/28/25			
3/14/25-	440-455 Walnut	Restoration	Restoration remains (mobilize to area once
3/28/25			Broadway completed) – C&M
3/14/25-	400-437 Walnut	CCTV, CIPP	Need to CCTV post repair (unable to due to Hard
3/28/25			Rock effort on Broadway) – C&M
3/14/25-	500 Walnut	Restoration	Pouring, site cleanup (mobilize to site once
3/28/25			Broadway completed) – C&M
3/14/25-	7000 Benajmin	Restoration	Pouring, site cleanup – C&M
3/28/25			
3/14/25-	500-300 Broadway	Restoration	Pouring, sidewalks, driveways (efforts on going) -
3/28/25			C&M

No tree impacts anticipated in the next 2 weeks

Full road closures are not anticipated, and roads traffic will resume uninterrupted at the conclusion of each work day; repairs are scheduled to take ~1day each.

MH rehab on-going BLD TRACKING: 91% COMPLETE